DOCKET NUMBER: 0083-0865-2/rlr

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

IN RE APPLICATION OF:

: GROUP: 2835

Masashi GOTOH, et al.

: ATTENTION:

SERIAL NUMBER: 09/119,626

Application Division Customer Corrections

FILED: July 21, 1998

FOR: CIRCUIT BOARD HAVING BONDING AREAS TO BE JOINED WITH BUMPS BY

ULTRASONIC BONDING

SECOND REQUEST FOR CORRECTED OFFICIAL FILING RECEIPT

Assistant Commissioner for Patents Washington, D.C. 20231

NOV 2 5 1998

Sir:

GPOUF 2100

The Patent Office is requested to provide a corrected Official Filing Receipt for the attached. If you have any questions, please do not hesitate to contact us.

No fees are required. However, in the event that a fee is required, please charge the appropriate amount to our Deposit Account No. 15-0030. A duplicate copy of this sheet is enclosed.

Respectfully submitted,

OBLON, SPIVAK, McCLELLAND, MAIER & NEUSTADT, P.C.

Marvin J. Spivak Attorney of Record

Registration Number 24,913 Robert F. Gnuss Registration Number 27,295

1755 S. Jefferson Davis Highway Arlington, Virginia 22202

(703) 413-3000 Fax: 413-2220

PTO-103X (Rev. 8-95)

FILING RECEIPT

UNITED STATES DEPARTMENT OF COMMERCE Patent and Trademark Office ASSISTANT SECRETARY AND COMMISSIONER OF PATENTS AND TRADEMARKS Washington, D.C. 20231

THN CORRECTED

APPLICATION NUMBER | FILING DATE | GRP ART UNIT | FIL FEE REC'D | ATTORNEY DOCKET NO. | DRWGS | TOT CL | IND CL

09/119.626 07/21/98 2835

\$920.00 0083-0865-2

RECEIVED

OBLON SPIVAK MCCLELLAND MAIER & NEUSTADT

NOV 2 5 1998

1755 JEFFERSON DAVIS HIGHWAY ARLINGTON VA 22202

GHUUF 2100

Receipt is acknowledged of this nonprovisional Petent Application. It will be considered in its order and you will be notified as to the results of the examination. Be sure to provide the U.S. APPLICATION INMEER, FILING DATE, NAME OF APPLICANT, end TITLE OF NIVETION when inquiring above this population. Fees treasmilled by Linear or drist see subject to collection, see welly the securacy of the data presented on this receipt. If an error is noted or the Title Receipt, please writs to the Application Processing Division's Customer Correction Branch without 10 days of receipt. Please provide a copy of the Pfiling Receipt with the Application Processing Division's control of the Pfiling Receipt with the Application Processing Division's control of the Pfiling Receipt with the Application Processing Division's control of the Pfiling Receipt with the Application Processing Division and the Pfiling Receipt with the Application Processing Division and Pfiling Receipt with the Application Pfiling Receipt Pfiling Rece

Applicant(s)

MASASHI GOTOH, TAKAHAGI-SHI, JAPAN; JITSUO KANAZAWA, TAKAHAGI-SHI, JAPAN; SYUICHIRO YAMAMOTO, NARASHINO-SHI, JAPAN; KENJI HONDA; TAKAHAGI-SHI, JAPAN.

FOREIGN APPLICATIONS- JAPAN

HEI. 9-210215 07/22/97

TITLE
CIRCUIT BOARD HAVING BONDING AREAS TO BE JOINED WITH BUMPS BY
ULTRASONCI BONDING

PRELIMINARY CLASS: 361

SECOND REQUEST

PLEASE NOTE THAT THE TITLE IS STILL INCORRECT, IT SHOULD READ AS FOLLOWS:

CIRCUIT BOARD HAVING BONDING AREAS TO BE JOINED WITH BUMPS BY ULTRASONIC BONDING

RECEIVED NOV 0 5 1998

OBLON, SPIVAK, McCLELLAND,